

References (Selection)



Year	Client	Description	Substances
2007	PRG Propylenpipeline Ruhr GmbH	Pipeline Marl-Scholven	Propylene
2007	BP Alaska	Pipeline Prudhoe Bay Alaska	Crude oil
2007	Bayer AG	Pipeline Köln-Dormagen	Carbon monoxide (CO)
2007	Airport Geneva (GVA)	Extension hydrant system	JET A1
2007	Hong Kong Town Gas LTD	Pipeline underground	Natural gas
2006	NATO	NATO Pipeline Aalen-Leipheim	Diesel / JET A1
2006	Hong Kong Town Gas LTD	Pipeline bundle underground	Natural gas
2005	NATO	NATO Pipeline Kehl-Tübingen	Fuels
2004	RWE	Tank farm Kalle	Methanol
2002	Stadtwerke Essen AG	Gas tanks underground (6x604m)	Natural gas
2002	Lausitzer Mitteldeutsche Bergverwaltung	Monitoring ground water decontamination	Water contaminations
2001	Kaiser GEOconsult GmbH	Contamination monitoring landfill	Contaminations
2001	Energieversorgung Oberhausen (EVO)	Gas tank underground (8x360m)	Natural gas
2001	Kaiser GEOconsult GmbH	Contamination monitoring military training area	Oil contaminations
2000	Kaiser GEOconsult GmbH	Contamination monitoring landfill	Contaminations
2000	Kaiser GEOconsult GmbH	Contamination monitoring airport	Jetfuel
2000	Ruhr Öl GmbH	Weigh-bridge monitoring	Contaminations
2000	Degussa AG	Chlorine Pipeline Lülsdorf-Wesseling	Liquid Chlorine
2000	Polski Koncern Naftowy S.A.	Tank farm	Fuel
2000	Stiefvater GmbH&Co KG	Monitoring waste treatment plant	Ground contaminations
1999	Transpetrol Bratislava	Druschba Pipeline	Crude oil
1999	BP Alaska	Offshore Pipeline "Northstar"	Crude oil
1998	Airport Zurich AG	Underground hydrant system	JET A1
1998	Airport Geneva (GVA)	Underground hydrant system	JET A1
1998	Transpetrol Bratislava	Druschba Pipeline	Crude oil
1998	BEWAG Berlin	Contamination monitoring industrial area	Oil Contaminations
1998	BSL/DOW Böhlen	Pipeline Rostock-Böhlen	Fuels
1998	Oslo Airport AS	Underground hydrant system	JET A1
1995	DuPont, Spain	Pipeline Asturias	Tetrahydrofurane
1995	SPP, Bratislava	Pipeline, above ground river crossing (pipe bridge)	Natural gas
1994	FES Schwabach	Contamination monitoring landfill	Ground contaminations
1994	IVG Oberhausen Neuburg/Donau	Monitoring cleaning area for tank wagons	Ground contaminations
1994	Geb. Gratz GmbH Austria	Contamination monitoring shredder	Ground contaminations
1994	Transpetrol Bratislava	Druschba Pipeline water protection area	Crude oil
1994	Clariant Spain	Pipeline Tarragona	Ethylene oxide
1994	VEBA Germany	Pipeline Bottrop	Fuels
1994	BP Gelsenkirchen Germany	Multiproduct monitoring pipeline bundle	Fuels
1993	Berliner Stadtreinigungsbetriebe	Contamination monitoring landfill	Contaminations
1991	Steyr AG Austria	Monitoring painting line	Ground contaminations
1991	Degussa Hüls AG	Multiproduct monitoring pipeline bundle	Ethylene, Methanol, C4-fractions, Parafines, Benzene, Cumol
1990	CIBA Geigy/Novartis, Basel	Tank farm (35 Tanks)	Hydro carbonates/ Aliphates
1990	VTG Hünxe	Multiproduct monitoring pipeline bundle	Fuel / Diesel
1989	Institut für Siedlungswasserbau Stuttgart	Contamination monitoring landfill	Chlorinated Hydrocarbons
	Pirelli Neustadt	Monitoring chemical stock	Methylene- / Ethylene-Ketones
1987			
1983	Wintershall AG Mannheim	Multiproduct monitoring pipeline bundle	C5,C9-fractions, Natural gas, Benzene, JET A1
1978	BASF AG Ludwigshafen	Ethylen Pipeline (twin pipe)	Ethylene
1978	BASF AG Ludwigshafen	Ethylen Pipeline	Ethylene